

123031

NHTBA-01-8876-2

807 Hampton Drive
Atlanta, GA 30350
February 9, 2001

DEPT. OF TRANSPORTATION

01 FEB 27 AM 6:35

RECEIVED

01 FEB 13 AM 11:58

OFFICE
DEFECTS INVESTIGATION

NHTSA-ODI
400 7th Street S.W.
Room 5318
Washington, DC 20590


To Whom It May Concern:

I am petitioning you to do research into the 1998-1999 Ford Escort, Escort ZX2 and the Mercury Tracer. I have pulled up on your sight many problems with the drivers side, as well as the passenger side, airbag not deploying upon impact.

I have called and written to Ford Motor Company about this problem with no results. They refuse to look into it.

Please help me!

Sincerely yours,



Randy D. Brantley

NATIONAL HIGHWAY
TRAFFIC SAFETY ADM.

1 2001 FEB 14 P 2:51

EXECUTIVE SECRETARIAT

CCM# 3253
ES:200102025